




Run 5075 mpwise, acc0: All




Run 5075 mpwise, acc0: Beam OFF




Run 5075, mpwise, acc0: Beam ON, Laser ON




Run 5075, mpwise, acc0: Beam ON, Laser OFF




Run 5075 mpwise, BCM: All




Run 5075 mpwise, BCM: Beam OFF




Run 5075, mpwise, BCM: Beam ON, Laser ON




Run 5075, mpwise, BCM: Beam ON, Laser OFF




Run 5075 mpwise, lasPow: All




Run 5075 mpwise, lasPow: Beam OFF




Run 5075, mpwise, lasPow: Beam ON, Laser ON




Run 5075, mpwise, lasPow: Beam ON, Laser OFF




Run 5075 mpwise, bpmAx: All




Run 5075 mpwise, bpmAx: Beam OFF




Run 5075, mpwise, bpmAx: Beam ON, Laser ON




Run 5075, mpwise, bpmAx: Beam ON, Laser OFF




Run 5075 mpwise, bpmAy: All




Run 5075 mpwise, bpmAy: Beam OFF




Run 5075, mpwise, bpmAy: Beam ON, Laser ON




Run 5075, mpwise, bpmAy: Beam ON, Laser OFF




Run 5075 mpswise, bpmBx: All




Run 5075 mpswise, bpmBx: Beam OFF



Run 5075, mpswise, bpmBx: Beam ON, Laser ON




Run 5075, mpswise, bpmBx: Beam ON, Laser OFF







Run 5075 mpswise, bpmBy: All




Run 5075 mpswise, bpmBy: Beam OFF




Run 5075, mpswise, bpmBy: Beam ON, Laser ON




Run 5075, mpswise, bpmBy: Beam ON, Laser OFF




Run 5075 mpwise, beam ON, laser ON




Run 5075 mpwise, beam ON, laser OFF



Run 5075 mpwise, beam OFF, laser ON




Run 5075 mpwise, beam OFF, laser OFF







Run 5075 mpwise, beam ON, laser ON




Run 5075 mpwise, beam ON, laser OFF




Run 5075 mpwise, beam OFF, laser ON




Run 5075 mpwise, beam OFF, laser OFF




Run 5075 mpwise, beam ON, laser ON




Run 5075 mpwise, beam ON, laser OFF




Run 5075 mpwise, beam OFF, laser ON




Run 5075 mpwise, beam OFF, laser OFF




Run 5075 mpwise, beam ON, laser ON




Run 5075 mpwise, beam ON, laser OFF




Run 5075 mpwise, beam OFF, laser ON




Run 5075 mpwise, beam OFF, laser OFF




Run 5075 mpwise, beam ON, laser ON




Run 5075 mpwise, beam ON, laser OFF




Run 5075 mpwise, beam OFF, laser ON




Run 5075 mpwise, beam OFF, laser OFF




Run 5075 mpwise, beam ON, laser ON




Run 5075 mpwise, beam ON, laser OFF




Run 5075 mpwise, beam OFF, laser ON




Run 5075 mpwise, beam OFF, laser OFF




Run 5075 mpwise, beam ON, laser ON



Run 5075 mpwise, beam ON, laser OFF



Run 5075 mpwise, beam OFF, laser ON



Run 5075 mpwise, beam OFF, laser OFF

