




Run 5285 mpwise, acc0: All




Run 5285 mpwise, acc0: Beam OFF




Run 5285, mpwise, acc0: Beam ON, Laser ON




Run 5285, mpwise, acc0: Beam ON, Laser OFF




Run 5285 mpwise, BCM: All




Run 5285 mpwise, BCM: Beam OFF




Run 5285, mpwise, BCM: Beam ON, Laser ON




Run 5285, mpwise, BCM: Beam ON, Laser OFF




Run 5285 mpwise, lasPow: All




Run 5285 mpwise, lasPow: Beam OFF




Run 5285, mpwise, lasPow: Beam ON, Laser ON




Run 5285, mpwise, lasPow: Beam ON, Laser OFF




Run 5285 mpswise, bpmAx: All




Run 5285 mpswise, bpmAx: Beam OFF




Run 5285, mpswise, bpmAx: Beam ON, Laser ON




Run 5285, mpswise, bpmAx: Beam ON, Laser OFF




Run 5285 mpwise, bpmAy: All




Run 5285 mpwise, bpmAy: Beam OFF




Run 5285, mpwise, bpmAy: Beam ON, Laser ON




Run 5285, mpwise, bpmAy: Beam ON, Laser OFF




Run 5285 mpswise, bpmBx: All




Run 5285 mpswise, bpmBx: Beam OFF




Run 5285, mpswise, bpmBx: Beam ON, Laser ON




Run 5285, mpswise, bpmBx: Beam ON, Laser OFF




Run 5285 mpswise, bpmBy: All




Run 5285 mpswise, bpmBy: Beam OFF




Run 5285, mpswise, bpmBy: Beam ON, Laser ON




Run 5285, mpswise, bpmBy: Beam ON, Laser OFF




Run 5285 mpwise, beam ON, laser ON




Run 5285 mpwise, beam ON, laser OFF




Run 5285 mpwise, beam OFF, laser ON




Run 5285 mpwise, beam OFF, laser OFF




Run 5285 mpwise, beam ON, laser ON




Run 5285 mpwise, beam ON, laser OFF




Run 5285 mpwise, beam OFF, laser ON




Run 5285 mpwise, beam OFF, laser OFF




Run 5285 mpwise, beam ON, laser ON




Run 5285 mpwise, beam ON, laser OFF




Run 5285 mpwise, beam OFF, laser ON




Run 5285 mpwise, beam OFF, laser OFF




Run 5285 mpwise, beam ON, laser ON




Run 5285 mpwise, beam ON, laser OFF




Run 5285 mpwise, beam OFF, laser ON




Run 5285 mpwise, beam OFF, laser OFF




Run 5285 mpwise, beam ON, laser ON




Run 5285 mpwise, beam ON, laser OFF




Run 5285 mpwise, beam OFF, laser ON




Run 5285 mpwise, beam OFF, laser OFF




Run 5285 mpwise, beam ON, laser ON




Run 5285 mpwise, beam ON, laser OFF




Run 5285 mpwise, beam OFF, laser ON




Run 5285 mpwise, beam OFF, laser OFF




Run 5285 mpwise, beam ON, laser ON



Run 5285 mpwise, beam ON, laser OFF



Run 5285 mpwise, beam OFF, laser ON



Run 5285 mpwise, beam OFF, laser OFF

