




Run 5337 mpwise, acc0: All




Run 5337 mpwise, acc0: Beam OFF




Run 5337, mpwise, acc0: Beam ON, Laser ON




Run 5337, mpwise, acc0: Beam ON, Laser OFF




Run 5337 mpwise, BCM: All




Run 5337 mpwise, BCM: Beam OFF




Run 5337, mpwise, BCM: Beam ON, Laser ON




Run 5337, mpwise, BCM: Beam ON, Laser OFF




Run 5337 mpwise, lasPow: All




Run 5337 mpwise, lasPow: Beam OFF




Run 5337, mpwise, lasPow: Beam ON, Laser ON




Run 5337, mpwise, lasPow: Beam ON, Laser OFF




Run 5337 mpswise, bpmAx: All




Run 5337 mpswise, bpmAx: Beam OFF




Run 5337, mpswise, bpmAx: Beam ON, Laser ON




Run 5337, mpswise, bpmAx: Beam ON, Laser OFF




Run 5337 mpwise, bpmAy: All




Run 5337 mpwise, bpmAy: Beam OFF




Run 5337, mpwise, bpmAy: Beam ON, Laser ON




Run 5337, mpwise, bpmAy: Beam ON, Laser OFF




Run 5337 mpswise, bpmBx: All




Run 5337 mpswise, bpmBx: Beam OFF




Run 5337, mpswise, bpmBx: Beam ON, Laser ON




Run 5337, mpswise, bpmBx: Beam ON, Laser OFF




Run 5337 mpwise, bpmBy: All




Run 5337 mpwise, bpmBy: Beam OFF




Run 5337, mpwise, bpmBy: Beam ON, Laser ON




Run 5337, mpwise, bpmBy: Beam ON, Laser OFF




Run 5337 mpwise, beam ON, laser ON




Run 5337 mpwise, beam ON, laser OFF




Run 5337 mpwise, beam OFF, laser ON




Run 5337 mpwise, beam OFF, laser OFF




Run 5337 mpwise, beam ON, laser ON




Run 5337 mpwise, beam ON, laser OFF




Run 5337 mpwise, beam OFF, laser ON




Run 5337 mpwise, beam OFF, laser OFF




Run 5337 mpwise, beam ON, laser ON




Run 5337 mpwise, beam ON, laser OFF




Run 5337 mpwise, beam OFF, laser ON




Run 5337 mpwise, beam OFF, laser OFF




Run 5337 mpwise, beam ON, laser ON




Run 5337 mpwise, beam ON, laser OFF




Run 5337 mpwise, beam OFF, laser ON




Run 5337 mpwise, beam OFF, laser OFF




Run 5337 mpwise, beam ON, laser ON




Run 5337 mpwise, beam ON, laser OFF




Run 5337 mpwise, beam OFF, laser ON




Run 5337 mpwise, beam OFF, laser OFF




Run 5337 mpwise, beam ON, laser ON




Run 5337 mpwise, beam ON, laser OFF




Run 5337 mpwise, beam OFF, laser ON




Run 5337 mpwise, beam OFF, laser OFF




Run 5337 mpwise, beam ON, laser ON



Run 5337 mpwise, beam ON, laser OFF



Run 5337 mpwise, beam OFF, laser ON



Run 5337 mpwise, beam OFF, laser OFF

