




Run 5518 mpwise, acc0: All




Run 5518 mpwise, acc0: Beam OFF




Run 5518, mpwise, acc0: Beam ON, Laser ON




Run 5518, mpwise, acc0: Beam ON, Laser OFF




Run 5518 mpwise, BCM: All




Run 5518 mpwise, BCM: Beam OFF




Run 5518, mpwise, BCM: Beam ON, Laser ON




Run 5518, mpwise, BCM: Beam ON, Laser OFF




Run 5518 mpwise, lasPow: All




Run 5518 mpwise, lasPow: Beam OFF




Run 5518, mpwise, lasPow: Beam ON, Laser ON




Run 5518, mpwise, lasPow: Beam ON, Laser OFF




Run 5518 mpwise, bpmAx: All




Run 5518 mpwise, bpmAx: Beam OFF




Run 5518, mpwise, bpmAx: Beam ON, Laser ON




Run 5518, mpwise, bpmAx: Beam ON, Laser OFF




Run 5518 mpwise, bpmAy: All




Run 5518 mpwise, bpmAy: Beam OFF




Run 5518, mpwise, bpmAy: Beam ON, Laser ON




Run 5518, mpwise, bpmAy: Beam ON, Laser OFF




Run 5518 mpswise, bpmBx: All




Run 5518 mpswise, bpmBx: Beam OFF




Run 5518, mpswise, bpmBx: Beam ON, Laser ON




Run 5518, mpswise, bpmBx: Beam ON, Laser OFF




Run 5518 mpswise, bpmBy: All




Run 5518 mpswise, bpmBy: Beam OFF




Run 5518, mpswise, bpmBy: Beam ON, Laser ON




Run 5518, mpswise, bpmBy: Beam ON, Laser OFF




Run 5518 mpwise, beam ON, laser ON




Run 5518 mpwise, beam ON, laser OFF




Run 5518 mpwise, beam OFF, laser ON




Run 5518 mpwise, beam ON, laser ON




Run 5518 mpwise, beam ON, laser OFF




Run 5518 mpwise, beam OFF, laser ON




Run 5518 mpwise, beam ON, laser ON




Run 5518 mpwise, beam ON, laser OFF




Run 5518 mpwise, beam OFF, laser ON




Run 5518 mpswise, beam ON, laser ON




Run 5518 mpswise, beam ON, laser OFF




Run 5518 mpswise, beam OFF, laser ON




Run 5518 mpwise, beam ON, laser ON




Run 5518 mpwise, beam ON, laser OFF




Run 5518 mpwise, beam OFF, laser ON




Run 5518 mpwise, beam ON, laser ON




Run 5518 mpwise, beam ON, laser OFF




Run 5518 mpwise, beam OFF, laser ON



Run 5518 mpwise, beam ON, laser ON



Run 5518 mpwise, beam ON, laser OFF



Run 5518 mpwise, beam OFF, laser ON

