




Run 5572 mpwise, acc0: All




Run 5572 mpwise, acc0: Beam OFF




Run 5572, mpwise, acc0: Beam ON, Laser ON




Run 5572, mpwise, acc0: Beam ON, Laser OFF




Run 5572 mpwise, BCM: All




Run 5572 mpwise, BCM: Beam OFF




Run 5572, mpwise, BCM: Beam ON, Laser ON




Run 5572, mpwise, BCM: Beam ON, Laser OFF




Run 5572 mpwise, lasPow: All




Run 5572 mpwise, lasPow: Beam OFF




Run 5572, mpwise, lasPow: Beam ON, Laser ON




Run 5572, mpwise, lasPow: Beam ON, Laser OFF




Run 5572 mpswise, bpmAx: All




Run 5572 mpswise, bpmAx: Beam OFF




Run 5572, mpswise, bpmAx: Beam ON, Laser ON




Run 5572, mpswise, bpmAx: Beam ON, Laser OFF




Run 5572 mpwise, bpmAy: All




Run 5572 mpwise, bpmAy: Beam OFF




Run 5572, mpwise, bpmAy: Beam ON, Laser ON




Run 5572, mpwise, bpmAy: Beam ON, Laser OFF




Run 5572 mpswise, bpmBx: All




Run 5572 mpswise, bpmBx: Beam OFF




Run 5572, mpswise, bpmBx: Beam ON, Laser ON




Run 5572, mpswise, bpmBx: Beam ON, Laser OFF




Run 5572 mpwise, bpmBy: All




Run 5572 mpwise, bpmBy: Beam OFF




Run 5572, mpwise, bpmBy: Beam ON, Laser ON




Run 5572, mpwise, bpmBy: Beam ON, Laser OFF




Run 5572 mpwise, beam ON, laser ON




Run 5572 mpwise, beam ON, laser OFF




Run 5572 mpwise, beam OFF, laser ON




Run 5572 mpwise, beam OFF, laser OFF




Run 5572 mpwise, beam ON, laser ON




Run 5572 mpwise, beam ON, laser OFF




Run 5572 mpwise, beam OFF, laser ON




Run 5572 mpwise, beam OFF, laser OFF




Run 5572 mpwise, beam ON, laser ON




Run 5572 mpwise, beam ON, laser OFF




Run 5572 mpwise, beam OFF, laser ON




Run 5572 mpwise, beam OFF, laser OFF




Run 5572 mpwise, beam ON, laser ON




Run 5572 mpwise, beam ON, laser OFF




Run 5572 mpwise, beam OFF, laser ON




Run 5572 mpwise, beam OFF, laser OFF




Run 5572 mpwise, beam ON, laser ON




Run 5572 mpwise, beam ON, laser OFF




Run 5572 mpwise, beam OFF, laser ON




Run 5572 mpwise, beam OFF, laser OFF




Run 5572 mpwise, beam ON, laser ON




Run 5572 mpwise, beam ON, laser OFF




Run 5572 mpwise, beam OFF, laser ON




Run 5572 mpwise, beam OFF, laser OFF




Run 5572 mpwise, beam ON, laser ON



Run 5572 mpwise, beam ON, laser OFF



Run 5572 mpwise, beam OFF, laser ON



Run 5572 mpwise, beam OFF, laser OFF

