




Run 5623 mpwise, acc0: All




Run 5623 mpwise, acc0: Beam OFF




Run 5623, mpwise, acc0: Beam ON, Laser ON




Run 5623, mpwise, acc0: Beam ON, Laser OFF




Run 5623 mpswise, BCM: All




Run 5623 mpswise, BCM: Beam OFF




Run 5623, mpswise, BCM: Beam ON, Laser ON




Run 5623, mpswise, BCM: Beam ON, Laser OFF




Run 5623 mpwise, lasPow: All




Run 5623 mpwise, lasPow: Beam OFF




Run 5623, mpwise, lasPow: Beam ON, Laser ON




Run 5623, mpwise, lasPow: Beam ON, Laser OFF




Run 5623 mpswise, bpmAx: All




Run 5623 mpswise, bpmAx: Beam OFF




Run 5623, mpswise, bpmAx: Beam ON, Laser ON




Run 5623, mpswise, bpmAx: Beam ON, Laser OFF




Run 5623 mpswise, bpmAy: All




Run 5623 mpswise, bpmAy: Beam OFF




Run 5623, mpswise, bpmAy: Beam ON, Laser ON




Run 5623, mpswise, bpmAy: Beam ON, Laser OFF




Run 5623 mpswise, bpmBx: All




Run 5623 mpswise, bpmBx: Beam OFF




Run 5623, mpswise, bpmBx: Beam ON, Laser ON




Run 5623, mpswise, bpmBx: Beam ON, Laser OFF




Run 5623 mpwise, bpmBy: All




Run 5623 mpwise, bpmBy: Beam OFF




Run 5623, mpwise, bpmBy: Beam ON, Laser ON




Run 5623, mpwise, bpmBy: Beam ON, Laser OFF




Run 5623 mpwise, beam ON, laser ON




Run 5623 mpwise, beam ON, laser OFF




Run 5623 mpwise, beam ON, laser ON




Run 5623 mpwise, beam ON, laser OFF




Run 5623 mpwise, beam ON, laser ON




Run 5623 mpwise, beam ON, laser OFF




Run 5623 mpwise, beam ON, laser ON




Run 5623 mpwise, beam ON, laser OFF




Run 5623 mpswise, beam ON, laser ON




Run 5623 mpswise, beam ON, laser OFF




Run 5623 mpswise, beam ON, laser ON



Run 5623 mpswise, beam ON, laser OFF



Run 5623 mpswise, beam ON, laser ON



Run 5623 mpswise, beam ON, laser OFF

