




Run 5759 mpwise, acc0: All




Run 5759 mpwise, acc0: Beam OFF




Run 5759, mpwise, acc0: Beam ON, Laser ON




Run 5759, mpwise, acc0: Beam ON, Laser OFF




Run 5759 mpwise, BCM: All




Run 5759 mpwise, BCM: Beam OFF




Run 5759, mpwise, BCM: Beam ON, Laser ON




Run 5759, mpwise, BCM: Beam ON, Laser OFF




Run 5759 mpwise, lasPow: All




Run 5759 mpwise, lasPow: Beam OFF




Run 5759, mpwise, lasPow: Beam ON, Laser ON




Run 5759, mpwise, lasPow: Beam ON, Laser OFF




Run 5759 mpwise, bpmAx: All




Run 5759 mpwise, bpmAx: Beam OFF




Run 5759, mpwise, bpmAx: Beam ON, Laser ON




Run 5759, mpwise, bpmAx: Beam ON, Laser OFF




Run 5759 mpwise, bpmAy: All




Run 5759 mpwise, bpmAy: Beam OFF




Run 5759, mpwise, bpmAy: Beam ON, Laser ON




Run 5759, mpwise, bpmAy: Beam ON, Laser OFF




Run 5759 mpswise, bpmBx: All




Run 5759 mpswise, bpmBx: Beam OFF




Run 5759, mpswise, bpmBx: Beam ON, Laser ON




Run 5759, mpswise, bpmBx: Beam ON, Laser OFF




Run 5759 mpswise, bpmBy: All




Run 5759 mpswise, bpmBy: Beam OFF




Run 5759, mpswise, bpmBy: Beam ON, Laser ON




Run 5759, mpswise, bpmBy: Beam ON, Laser OFF




Run 5759 mpwise, beam ON, laser ON




Run 5759 mpwise, beam ON, laser OFF




Run 5759 mpwise, beam OFF, laser ON




Run 5759 mpwise, beam OFF, laser OFF




Run 5759 mpwise, beam ON, laser ON




Run 5759 mpwise, beam ON, laser OFF




Run 5759 mpwise, beam OFF, laser ON




Run 5759 mpwise, beam OFF, laser OFF




Run 5759 mpwise, beam ON, laser ON




Run 5759 mpwise, beam ON, laser OFF




Run 5759 mpwise, beam OFF, laser ON




Run 5759 mpwise, beam OFF, laser OFF




Run 5759 mpwise, beam ON, laser ON




Run 5759 mpwise, beam ON, laser OFF




Run 5759 mpwise, beam OFF, laser ON




Run 5759 mpwise, beam OFF, laser OFF




Run 5759 mpwise, beam ON, laser ON




Run 5759 mpwise, beam ON, laser OFF




Run 5759 mpwise, beam OFF, laser ON




Run 5759 mpwise, beam OFF, laser OFF




Run 5759 mpwise, beam ON, laser ON




Run 5759 mpwise, beam ON, laser OFF




Run 5759 mpwise, beam OFF, laser ON




Run 5759 mpwise, beam OFF, laser OFF




Run 5759 mpwise, beam ON, laser ON



Run 5759 mpwise, beam ON, laser OFF



Run 5759 mpwise, beam OFF, laser ON



Run 5759 mpwise, beam OFF, laser OFF

