




Run 5920 mpwise, acc0: All




Run 5920 mpwise, acc0: Beam OFF




Run 5920, mpwise, acc0: Beam ON, Laser ON




Run 5920, mpwise, acc0: Beam ON, Laser OFF




Run 5920 mpwise, BCM: All




Run 5920 mpwise, BCM: Beam OFF




Run 5920, mpwise, BCM: Beam ON, Laser ON




Run 5920, mpwise, BCM: Beam ON, Laser OFF




Run 5920 mpswise, lasPow: All




Run 5920 mpswise, lasPow: Beam OFF




Run 5920, mpswise, lasPow: Beam ON, Laser ON




Run 5920, mpswise, lasPow: Beam ON, Laser OFF




Run 5920 mpwise, bpmAx: All




Run 5920 mpwise, bpmAx: Beam OFF




Run 5920, mpwise, bpmAx: Beam ON, Laser ON




Run 5920, mpwise, bpmAx: Beam ON, Laser OFF




Run 5920 mpwise, bpmAy: All




Run 5920 mpwise, bpmAy: Beam OFF




Run 5920, mpwise, bpmAy: Beam ON, Laser ON




Run 5920, mpwise, bpmAy: Beam ON, Laser OFF




Run 5920 mpswise, bpmBx: All




Run 5920 mpswise, bpmBx: Beam OFF




Run 5920, mpswise, bpmBx: Beam ON, Laser ON




Run 5920, mpswise, bpmBx: Beam ON, Laser OFF




Run 5920 mpswise, bpmBy: All




Run 5920 mpswise, bpmBy: Beam OFF




Run 5920, mpswise, bpmBy: Beam ON, Laser ON




Run 5920, mpswise, bpmBy: Beam ON, Laser OFF




Run 5920 mpwise, beam ON, laser ON




Run 5920 mpwise, beam ON, laser OFF




Run 5920 mpwise, beam OFF, laser ON




Run 5920 mpwise, beam OFF, laser OFF




Run 5920 mpwise, beam ON, laser ON




Run 5920 mpwise, beam ON, laser OFF




Run 5920 mpwise, beam OFF, laser ON




Run 5920 mpwise, beam OFF, laser OFF




Run 5920 mpwise, beam ON, laser ON




Run 5920 mpwise, beam ON, laser OFF




Run 5920 mpwise, beam OFF, laser ON




Run 5920 mpwise, beam OFF, laser OFF




Run 5920 mpwise, beam ON, laser ON




Run 5920 mpwise, beam ON, laser OFF




Run 5920 mpwise, beam OFF, laser ON




Run 5920 mpwise, beam OFF, laser OFF




Run 5920 mpwise, beam ON, laser ON




Run 5920 mpwise, beam ON, laser OFF




Run 5920 mpwise, beam OFF, laser ON




Run 5920 mpwise, beam OFF, laser OFF




Run 5920 mpwise, beam ON, laser ON




Run 5920 mpwise, beam ON, laser OFF




Run 5920 mpwise, beam OFF, laser ON




Run 5920 mpwise, beam OFF, laser OFF




Run 5920 mpwise, beam ON, laser ON



Run 5920 mpwise, beam ON, laser OFF



Run 5920 mpwise, beam OFF, laser ON



Run 5920 mpwise, beam OFF, laser OFF

