




Run 5926 mpwise, acc0: All




Run 5926 mpwise, acc0: Beam OFF




Run 5926, mpwise, acc0: Beam ON, Laser ON




Run 5926, mpwise, acc0: Beam ON, Laser OFF




Run 5926 mpwise, BCM: All




Run 5926 mpwise, BCM: Beam OFF




Run 5926, mpwise, BCM: Beam ON, Laser ON




Run 5926, mpwise, BCM: Beam ON, Laser OFF




Run 5926 mpswise, lasPow: All




Run 5926 mpswise, lasPow: Beam OFF




Run 5926, mpswise, lasPow: Beam ON, Laser ON




Run 5926, mpswise, lasPow: Beam ON, Laser OFF




Run 5926 mpwise, bpmAx: All




Run 5926 mpwise, bpmAx: Beam OFF




Run 5926, mpwise, bpmAx: Beam ON, Laser ON




Run 5926, mpwise, bpmAx: Beam ON, Laser OFF




Run 5926 mpwise, bpmAy: All




Run 5926 mpwise, bpmAy: Beam OFF




Run 5926, mpwise, bpmAy: Beam ON, Laser ON




Run 5926, mpwise, bpmAy: Beam ON, Laser OFF




Run 5926 mpwise, bpmBx: All




Run 5926 mpwise, bpmBx: Beam OFF




Run 5926, mpwise, bpmBx: Beam ON, Laser ON




Run 5926, mpwise, bpmBx: Beam ON, Laser OFF




Run 5926 mpswise, bpmBy: All




Run 5926 mpswise, bpmBy: Beam OFF




Run 5926, mpswise, bpmBy: Beam ON, Laser ON




Run 5926, mpswise, bpmBy: Beam ON, Laser OFF




Run 5926 mpwise, beam ON, laser ON




Run 5926 mpwise, beam ON, laser OFF




Run 5926 mpwise, beam OFF, laser ON




Run 5926 mpwise, beam OFF, laser OFF




Run 5926 mpwise, beam ON, laser ON




Run 5926 mpwise, beam ON, laser OFF




Run 5926 mpwise, beam OFF, laser ON




Run 5926 mpwise, beam OFF, laser OFF




Run 5926 mpwise, beam ON, laser ON




Run 5926 mpwise, beam ON, laser OFF




Run 5926 mpwise, beam OFF, laser ON




Run 5926 mpwise, beam OFF, laser OFF




Run 5926 mpwise, beam ON, laser ON




Run 5926 mpwise, beam ON, laser OFF




Run 5926 mpwise, beam OFF, laser ON




Run 5926 mpwise, beam OFF, laser OFF




Run 5926 mpwise, beam ON, laser ON




Run 5926 mpwise, beam ON, laser OFF




Run 5926 mpwise, beam OFF, laser ON




Run 5926 mpwise, beam OFF, laser OFF




Run 5926 mpwise, beam ON, laser ON




Run 5926 mpwise, beam ON, laser OFF




Run 5926 mpwise, beam OFF, laser ON




Run 5926 mpwise, beam OFF, laser OFF




Run 5926 mpwise, beam ON, laser ON



Run 5926 mpwise, beam ON, laser OFF



Run 5926 mpwise, beam OFF, laser ON



Run 5926 mpwise, beam OFF, laser OFF

