




Run 6022 mpwise, acc0: All




Run 6022 mpwise, acc0: Beam OFF




Run 6022, mpwise, acc0: Beam ON, Laser ON




Run 6022, mpwise, acc0: Beam ON, Laser OFF




Run 6022 mpswise, BCM: All




Run 6022 mpswise, BCM: Beam OFF




Run 6022, mpswise, BCM: Beam ON, Laser ON




Run 6022, mpswise, BCM: Beam ON, Laser OFF




Run 6022 mpswise, lasPow: All




Run 6022 mpswise, lasPow: Beam OFF




Run 6022, mpswise, lasPow: Beam ON, Laser ON




Run 6022, mpswise, lasPow: Beam ON, Laser OFF




Run 6022 mpwise, bpmAx: All




Run 6022 mpwise, bpmAx: Beam OFF




Run 6022, mpwise, bpmAx: Beam ON, Laser ON




Run 6022, mpwise, bpmAx: Beam ON, Laser OFF




Run 6022 mpwise, bpmAy: All




Run 6022 mpwise, bpmAy: Beam OFF




Run 6022, mpwise, bpmAy: Beam ON, Laser ON




Run 6022, mpwise, bpmAy: Beam ON, Laser OFF




Run 6022 mpswise, bpmBx: All




Run 6022 mpswise, bpmBx: Beam OFF




Run 6022, mpswise, bpmBx: Beam ON, Laser ON




Run 6022, mpswise, bpmBx: Beam ON, Laser OFF




Run 6022 mpwise, bpmBy: All




Run 6022 mpwise, bpmBy: Beam OFF




Run 6022, mpwise, bpmBy: Beam ON, Laser ON




Run 6022, mpwise, bpmBy: Beam ON, Laser OFF




Run 6022 mpwise, beam ON, laser ON




Run 6022 mpwise, beam ON, laser OFF




Run 6022 mpwise, beam OFF, laser ON




Run 6022 mpwise, beam OFF, laser OFF




Run 6022 mpwise, beam ON, laser ON




Run 6022 mpwise, beam ON, laser OFF




Run 6022 mpwise, beam OFF, laser ON




Run 6022 mpwise, beam OFF, laser OFF




Run 6022 mpwise, beam ON, laser ON




Run 6022 mpwise, beam ON, laser OFF




Run 6022 mpwise, beam OFF, laser ON




Run 6022 mpwise, beam OFF, laser OFF




Run 6022 mpwise, beam ON, laser ON




Run 6022 mpwise, beam ON, laser OFF




Run 6022 mpwise, beam OFF, laser ON




Run 6022 mpwise, beam OFF, laser OFF




Run 6022 mpwise, beam ON, laser ON




Run 6022 mpwise, beam ON, laser OFF




Run 6022 mpwise, beam OFF, laser ON




Run 6022 mpwise, beam OFF, laser OFF




Run 6022 mpwise, beam ON, laser ON




Run 6022 mpwise, beam ON, laser OFF




Run 6022 mpwise, beam OFF, laser ON




Run 6022 mpwise, beam OFF, laser OFF




Run 6022 mpwise, beam ON, laser ON



Run 6022 mpwise, beam ON, laser OFF



Run 6022 mpwise, beam OFF, laser ON



Run 6022 mpwise, beam OFF, laser OFF

