




Run 6025 mpwise, acc0: All




Run 6025 mpwise, acc0: Beam OFF




Run 6025, mpwise, acc0: Beam ON, Laser ON




Run 6025, mpwise, acc0: Beam ON, Laser OFF




Run 6025 mpwise, BCM: All




Run 6025 mpwise, BCM: Beam OFF




Run 6025, mpwise, BCM: Beam ON, Laser ON




Run 6025, mpwise, BCM: Beam ON, Laser OFF




Run 6025 mpswise, lasPow: All




Run 6025 mpswise, lasPow: Beam OFF




Run 6025, mpswise, lasPow: Beam ON, Laser ON




Run 6025, mpswise, lasPow: Beam ON, Laser OFF




Run 6025 mpwise, bpmAx: All




Run 6025 mpwise, bpmAx: Beam OFF




Run 6025, mpwise, bpmAx: Beam ON, Laser ON




Run 6025, mpwise, bpmAx: Beam ON, Laser OFF




Run 6025 mpwise, bpmAy: All




Run 6025 mpwise, bpmAy: Beam OFF




Run 6025, mpwise, bpmAy: Beam ON, Laser ON




Run 6025, mpwise, bpmAy: Beam ON, Laser OFF




Run 6025 mpwise, bpmBx: All




Run 6025 mpwise, bpmBx: Beam OFF




Run 6025, mpwise, bpmBx: Beam ON, Laser ON




Run 6025, mpwise, bpmBx: Beam ON, Laser OFF




Run 6025 mpswise, bpmBy: All




Run 6025 mpswise, bpmBy: Beam OFF




Run 6025, mpswise, bpmBy: Beam ON, Laser ON




Run 6025, mpswise, bpmBy: Beam ON, Laser OFF




Run 6025 mpwise, beam ON, laser ON




Run 6025 mpwise, beam ON, laser OFF




Run 6025 mpwise, beam OFF, laser ON




Run 6025 mpwise, beam OFF, laser OFF




Run 6025 mpwise, beam ON, laser ON




Run 6025 mpwise, beam ON, laser OFF




Run 6025 mpwise, beam OFF, laser ON




Run 6025 mpwise, beam OFF, laser OFF




Run 6025 mpwise, beam ON, laser ON




Run 6025 mpwise, beam ON, laser OFF




Run 6025 mpwise, beam OFF, laser ON




Run 6025 mpwise, beam OFF, laser OFF




Run 6025 mpwise, beam ON, laser ON




Run 6025 mpwise, beam ON, laser OFF




Run 6025 mpwise, beam OFF, laser ON




Run 6025 mpwise, beam OFF, laser OFF




Run 6025 mpwise, beam ON, laser ON




Run 6025 mpwise, beam ON, laser OFF




Run 6025 mpwise, beam OFF, laser ON




Run 6025 mpwise, beam OFF, laser OFF




Run 6025 mpwise, beam ON, laser ON




Run 6025 mpwise, beam ON, laser OFF




Run 6025 mpwise, beam OFF, laser ON




Run 6025 mpwise, beam OFF, laser OFF




Run 6025 mpwise, beam ON, laser ON



Run 6025 mpwise, beam ON, laser OFF



Run 6025 mpwise, beam OFF, laser ON



Run 6025 mpwise, beam OFF, laser OFF

