




Run 6031 mpwise, acc0: All




Run 6031 mpwise, acc0: Beam OFF




Run 6031, mpwise, acc0: Beam ON, Laser ON




Run 6031, mpwise, acc0: Beam ON, Laser OFF




Run 6031 mpwise, BCM: All




Run 6031 mpwise, BCM: Beam OFF




Run 6031, mpwise, BCM: Beam ON, Laser ON




Run 6031, mpwise, BCM: Beam ON, Laser OFF




Run 6031 mpswise, lasPow: All




Run 6031 mpswise, lasPow: Beam OFF




Run 6031, mpswise, lasPow: Beam ON, Laser ON




Run 6031, mpswise, lasPow: Beam ON, Laser OFF




Run 6031 mpwise, bpmAx: All




Run 6031 mpwise, bpmAx: Beam OFF




Run 6031, mpwise, bpmAx: Beam ON, Laser ON




Run 6031, mpwise, bpmAx: Beam ON, Laser OFF




Run 6031 mpwise, bpmAy: All




Run 6031 mpwise, bpmAy: Beam OFF




Run 6031, mpwise, bpmAy: Beam ON, Laser ON




Run 6031, mpwise, bpmAy: Beam ON, Laser OFF




Run 6031 mpswise, bpmBx: All




Run 6031 mpswise, bpmBx: Beam OFF




Run 6031, mpswise, bpmBx: Beam ON, Laser ON




Run 6031, mpswise, bpmBx: Beam ON, Laser OFF




Run 6031 mpswise, bpmBy: All




Run 6031 mpswise, bpmBy: Beam OFF




Run 6031, mpswise, bpmBy: Beam ON, Laser ON




Run 6031, mpswise, bpmBy: Beam ON, Laser OFF




Run 6031 mpswise, beam ON, laser ON




Run 6031 mpswise, beam ON, laser OFF




Run 6031 mpswise, beam OFF, laser ON




Run 6031 mpswise, beam OFF, laser OFF




Run 6031 mpwise, beam ON, laser ON




Run 6031 mpwise, beam ON, laser OFF




Run 6031 mpwise, beam OFF, laser ON




Run 6031 mpwise, beam OFF, laser OFF




Run 6031 mpwise, beam ON, laser ON




Run 6031 mpwise, beam ON, laser OFF




Run 6031 mpwise, beam OFF, laser ON




Run 6031 mpwise, beam OFF, laser OFF




Run 6031 mpwise, beam ON, laser ON




Run 6031 mpwise, beam ON, laser OFF




Run 6031 mpwise, beam OFF, laser ON




Run 6031 mpwise, beam OFF, laser OFF




Run 6031 mpwise, beam ON, laser ON




Run 6031 mpwise, beam ON, laser OFF




Run 6031 mpwise, beam OFF, laser ON




Run 6031 mpwise, beam OFF, laser OFF




Run 6031 mpwise, beam ON, laser ON




Run 6031 mpwise, beam ON, laser OFF




Run 6031 mpwise, beam OFF, laser ON




Run 6031 mpwise, beam OFF, laser OFF




Run 6031 mpwise, beam ON, laser ON



Run 6031 mpwise, beam ON, laser OFF



Run 6031 mpwise, beam OFF, laser ON



Run 6031 mpwise, beam OFF, laser OFF

