




Run 6074 mpwise, acc0: All




Run 6074 mpwise, acc0: Beam OFF




Run 6074, mpwise, acc0: Beam ON, Laser ON




Run 6074, mpwise, acc0: Beam ON, Laser OFF




Run 6074 mpwise, BCM: All




Run 6074 mpwise, BCM: Beam OFF




Run 6074, mpwise, BCM: Beam ON, Laser ON




Run 6074, mpwise, BCM: Beam ON, Laser OFF




Run 6074 mpwise, lasPow: All




Run 6074 mpwise, lasPow: Beam OFF




Run 6074, mpwise, lasPow: Beam ON, Laser ON




Run 6074, mpwise, lasPow: Beam ON, Laser OFF




Run 6074 mpwise, bpmAx: All




Run 6074 mpwise, bpmAx: Beam OFF




Run 6074, mpwise, bpmAx: Beam ON, Laser ON




Run 6074, mpwise, bpmAx: Beam ON, Laser OFF




Run 6074 mpwise, bpmAy: All




Run 6074 mpwise, bpmAy: Beam OFF




Run 6074, mpwise, bpmAy: Beam ON, Laser ON




Run 6074, mpwise, bpmAy: Beam ON, Laser OFF




Run 6074 mpwise, bpmBx: All




Run 6074 mpwise, bpmBx: Beam OFF




Run 6074, mpwise, bpmBx: Beam ON, Laser ON




Run 6074, mpwise, bpmBx: Beam ON, Laser OFF




Run 6074 mpwise, bpmBy: All




Run 6074 mpwise, bpmBy: Beam OFF




Run 6074, mpwise, bpmBy: Beam ON, Laser ON




Run 6074, mpwise, bpmBy: Beam ON, Laser OFF




Run 6074 mpwise, beam ON, laser ON




Run 6074 mpwise, beam ON, laser OFF




Run 6074 mpwise, beam OFF, laser ON




Run 6074 mpwise, beam OFF, laser OFF




Run 6074 mpwise, beam ON, laser ON




Run 6074 mpwise, beam ON, laser OFF




Run 6074 mpwise, beam OFF, laser ON




Run 6074 mpwise, beam OFF, laser OFF




Run 6074 mpwise, beam ON, laser ON




Run 6074 mpwise, beam ON, laser OFF




Run 6074 mpwise, beam OFF, laser ON




Run 6074 mpwise, beam OFF, laser OFF




Run 6074 mpwise, beam ON, laser ON




Run 6074 mpwise, beam ON, laser OFF




Run 6074 mpwise, beam OFF, laser ON




Run 6074 mpwise, beam OFF, laser OFF




Run 6074 mpwise, beam ON, laser ON




Run 6074 mpwise, beam ON, laser OFF




Run 6074 mpwise, beam OFF, laser ON




Run 6074 mpwise, beam OFF, laser OFF




Run 6074 mpwise, beam ON, laser ON




Run 6074 mpwise, beam ON, laser OFF




Run 6074 mpwise, beam OFF, laser ON




Run 6074 mpwise, beam OFF, laser OFF




Run 6074 mpwise, beam ON, laser ON



Run 6074 mpwise, beam ON, laser OFF



Run 6074 mpwise, beam OFF, laser ON



Run 6074 mpwise, beam OFF, laser OFF

