




Run 6089 mpwise, acc0: All




Run 6089 mpwise, acc0: Beam OFF




Run 6089, mpwise, acc0: Beam ON, Laser ON




Run 6089, mpwise, acc0: Beam ON, Laser OFF




Run 6089 mpwise, BCM: All




Run 6089 mpwise, BCM: Beam OFF




Run 6089, mpwise, BCM: Beam ON, Laser ON




Run 6089, mpwise, BCM: Beam ON, Laser OFF




Run 6089 mpwise, lasPow: All




Run 6089 mpwise, lasPow: Beam OFF




Run 6089, mpwise, lasPow: Beam ON, Laser ON




Run 6089, mpwise, lasPow: Beam ON, Laser OFF




Run 6089 mpwise, bpmAx: All




Run 6089 mpwise, bpmAx: Beam OFF




Run 6089, mpwise, bpmAx: Beam ON, Laser ON




Run 6089, mpwise, bpmAx: Beam ON, Laser OFF




Run 6089 mpwise, bpmAy: All




Run 6089 mpwise, bpmAy: Beam OFF




Run 6089, mpwise, bpmAy: Beam ON, Laser ON




Run 6089, mpwise, bpmAy: Beam ON, Laser OFF




Run 6089 mpswise, bpmBx: All




Run 6089 mpswise, bpmBx: Beam OFF




Run 6089, mpswise, bpmBx: Beam ON, Laser ON




Run 6089, mpswise, bpmBx: Beam ON, Laser OFF




Run 6089 mpswise, bpmBy: All




Run 6089 mpswise, bpmBy: Beam OFF




Run 6089, mpswise, bpmBy: Beam ON, Laser ON




Run 6089, mpswise, bpmBy: Beam ON, Laser OFF




Run 6089 mpwise, beam ON, laser ON




Run 6089 mpwise, beam ON, laser OFF




Run 6089 mpwise, beam OFF, laser ON




Run 6089 mpwise, beam OFF, laser OFF




Run 6089 mpwise, beam ON, laser ON




Run 6089 mpwise, beam ON, laser OFF




Run 6089 mpwise, beam OFF, laser ON




Run 6089 mpwise, beam OFF, laser OFF




Run 6089 mpwise, beam ON, laser ON




Run 6089 mpwise, beam ON, laser OFF




Run 6089 mpwise, beam OFF, laser ON




Run 6089 mpwise, beam OFF, laser OFF




Run 6089 mpwise, beam ON, laser ON




Run 6089 mpwise, beam ON, laser OFF




Run 6089 mpwise, beam OFF, laser ON




Run 6089 mpwise, beam OFF, laser OFF




Run 6089 mpwise, beam ON, laser ON




Run 6089 mpwise, beam ON, laser OFF




Run 6089 mpwise, beam OFF, laser ON




Run 6089 mpwise, beam OFF, laser OFF




Run 6089 mpwise, beam ON, laser ON




Run 6089 mpwise, beam ON, laser OFF




Run 6089 mpwise, beam OFF, laser ON




Run 6089 mpwise, beam OFF, laser OFF




Run 6089 mpwise, beam ON, laser ON



Run 6089 mpwise, beam ON, laser OFF



Run 6089 mpwise, beam OFF, laser ON



Run 6089 mpwise, beam OFF, laser OFF

