




Run 6131 mpwise, acc0: All




Run 6131 mpwise, acc0: Beam OFF




Run 6131, mpwise, acc0: Beam ON, Laser ON




Run 6131, mpwise, acc0: Beam ON, Laser OFF




Run 6131 mpwise, BCM: All




Run 6131 mpwise, BCM: Beam OFF




Run 6131, mpwise, BCM: Beam ON, Laser ON




Run 6131, mpwise, BCM: Beam ON, Laser OFF




Run 6131 mpwise, lasPow: All




Run 6131 mpwise, lasPow: Beam OFF




Run 6131, mpwise, lasPow: Beam ON, Laser ON




Run 6131, mpwise, lasPow: Beam ON, Laser OFF




Run 6131 mpwise, bpmAx: All




Run 6131 mpwise, bpmAx: Beam OFF




Run 6131, mpwise, bpmAx: Beam ON, Laser ON




Run 6131, mpwise, bpmAx: Beam ON, Laser OFF




Run 6131 mpwise, bpmAy: All




Run 6131 mpwise, bpmAy: Beam OFF




Run 6131, mpwise, bpmAy: Beam ON, Laser ON




Run 6131, mpwise, bpmAy: Beam ON, Laser OFF




Run 6131 mpwise, bpmBx: All




Run 6131 mpwise, bpmBx: Beam OFF




Run 6131, mpwise, bpmBx: Beam ON, Laser ON




Run 6131, mpwise, bpmBx: Beam ON, Laser OFF




Run 6131 mpwise, bpmBy: All




Run 6131 mpwise, bpmBy: Beam OFF




Run 6131, mpwise, bpmBy: Beam ON, Laser ON




Run 6131, mpwise, bpmBy: Beam ON, Laser OFF




Run 6131 mpwise, beam ON, laser ON




Run 6131 mpwise, beam ON, laser OFF




Run 6131 mpwise, beam OFF, laser ON




Run 6131 mpwise, beam OFF, laser OFF




Run 6131 mpwise, beam ON, laser ON




Run 6131 mpwise, beam ON, laser OFF




Run 6131 mpwise, beam OFF, laser ON




Run 6131 mpwise, beam OFF, laser OFF




Run 6131 mpwise, beam ON, laser ON




Run 6131 mpwise, beam ON, laser OFF




Run 6131 mpwise, beam OFF, laser ON




Run 6131 mpwise, beam OFF, laser OFF




Run 6131 mpwise, beam ON, laser ON




Run 6131 mpwise, beam ON, laser OFF




Run 6131 mpwise, beam OFF, laser ON




Run 6131 mpwise, beam OFF, laser OFF




Run 6131 mpwise, beam ON, laser ON




Run 6131 mpwise, beam ON, laser OFF




Run 6131 mpwise, beam OFF, laser ON




Run 6131 mpwise, beam OFF, laser OFF




Run 6131 mpwise, beam ON, laser ON




Run 6131 mpwise, beam ON, laser OFF




Run 6131 mpwise, beam OFF, laser ON




Run 6131 mpwise, beam OFF, laser OFF




Run 6131 mpwise, beam ON, laser ON



Run 6131 mpwise, beam ON, laser OFF



Run 6131 mpwise, beam OFF, laser ON



Run 6131 mpwise, beam OFF, laser OFF

