




Run 6157 mpwise, acc0: All




Run 6157 mpwise, acc0: Beam OFF




Run 6157, mpwise, acc0: Beam ON, Laser ON




Run 6157, mpwise, acc0: Beam ON, Laser OFF




Run 6157 mpwise, BCM: All




Run 6157 mpwise, BCM: Beam OFF




Run 6157, mpwise, BCM: Beam ON, Laser ON




Run 6157, mpwise, BCM: Beam ON, Laser OFF




Run 6157 mpwise, lasPow: All




Run 6157 mpwise, lasPow: Beam OFF




Run 6157, mpwise, lasPow: Beam ON, Laser ON




Run 6157, mpwise, lasPow: Beam ON, Laser OFF




Run 6157 mpwise, bpmAx: All




Run 6157 mpwise, bpmAx: Beam OFF




Run 6157, mpwise, bpmAx: Beam ON, Laser ON




Run 6157, mpwise, bpmAx: Beam ON, Laser OFF




Run 6157 mpwise, bpmAy: All




Run 6157 mpwise, bpmAy: Beam OFF




Run 6157, mpwise, bpmAy: Beam ON, Laser ON




Run 6157, mpwise, bpmAy: Beam ON, Laser OFF




Run 6157 mpwise, bpmBx: All




Run 6157 mpwise, bpmBx: Beam OFF



Run 6157, mpwise, bpmBx: Beam ON, Laser ON




Run 6157, mpwise, bpmBx: Beam ON, Laser OFF







Run 6157 mpwise, bpmBy: All




Run 6157 mpwise, bpmBy: Beam OFF




Run 6157, mpwise, bpmBy: Beam ON, Laser ON




Run 6157, mpwise, bpmBy: Beam ON, Laser OFF




Run 6157 mpwise, beam ON, laser ON




Run 6157 mpwise, beam ON, laser OFF



Run 6157 mpwise, beam OFF, laser ON




Run 6157 mpwise, beam OFF, laser OFF







Run 6157 mpwise, beam ON, laser ON




Run 6157 mpwise, beam ON, laser OFF




Run 6157 mpwise, beam OFF, laser ON




Run 6157 mpwise, beam OFF, laser OFF




Run 6157 mpwise, beam ON, laser ON




Run 6157 mpwise, beam ON, laser OFF




Run 6157 mpwise, beam OFF, laser ON




Run 6157 mpwise, beam OFF, laser OFF




Run 6157 mpwise, beam ON, laser ON




Run 6157 mpwise, beam ON, laser OFF




Run 6157 mpwise, beam OFF, laser ON




Run 6157 mpwise, beam OFF, laser OFF




Run 6157 mpwise, beam ON, laser ON




Run 6157 mpwise, beam ON, laser OFF




Run 6157 mpwise, beam OFF, laser ON




Run 6157 mpwise, beam OFF, laser OFF




Run 6157 mpwise, beam ON, laser ON




Run 6157 mpwise, beam ON, laser OFF




Run 6157 mpwise, beam OFF, laser ON




Run 6157 mpwise, beam OFF, laser OFF




Run 6157 mpwise, beam ON, laser ON



Run 6157 mpwise, beam ON, laser OFF



Run 6157 mpwise, beam OFF, laser ON



Run 6157 mpwise, beam OFF, laser OFF

