




Run 6161 mpwise, acc0: All




Run 6161 mpwise, acc0: Beam OFF




Run 6161, mpwise, acc0: Beam ON, Laser ON




Run 6161, mpwise, acc0: Beam ON, Laser OFF




Run 6161 mpwise, BCM: All




Run 6161 mpwise, BCM: Beam OFF




Run 6161, mpwise, BCM: Beam ON, Laser ON




Run 6161, mpwise, BCM: Beam ON, Laser OFF




Run 6161 mpwise, lasPow: All




Run 6161 mpwise, lasPow: Beam OFF




Run 6161, mpwise, lasPow: Beam ON, Laser ON




Run 6161, mpwise, lasPow: Beam ON, Laser OFF




Run 6161 mpwise, bpmAx: All




Run 6161 mpwise, bpmAx: Beam OFF




Run 6161, mpwise, bpmAx: Beam ON, Laser ON




Run 6161, mpwise, bpmAx: Beam ON, Laser OFF




Run 6161 mpwise, bpmAy: All




Run 6161 mpwise, bpmAy: Beam OFF




Run 6161, mpwise, bpmAy: Beam ON, Laser ON




Run 6161, mpwise, bpmAy: Beam ON, Laser OFF




Run 6161 mpswise, bpmBx: All




Run 6161 mpswise, bpmBx: Beam OFF




Run 6161, mpswise, bpmBx: Beam ON, Laser ON




Run 6161, mpswise, bpmBx: Beam ON, Laser OFF




Run 6161 mpswise, bpmBy: All




Run 6161 mpswise, bpmBy: Beam OFF




Run 6161, mpswise, bpmBy: Beam ON, Laser ON




Run 6161, mpswise, bpmBy: Beam ON, Laser OFF




Run 6161 mpwise, beam ON, laser ON




Run 6161 mpwise, beam ON, laser OFF




Run 6161 mpwise, beam OFF, laser ON




Run 6161 mpwise, beam OFF, laser OFF




Run 6161 mpwise, beam ON, laser ON




Run 6161 mpwise, beam ON, laser OFF




Run 6161 mpwise, beam OFF, laser ON




Run 6161 mpwise, beam OFF, laser OFF




Run 6161 mpwise, beam ON, laser ON




Run 6161 mpwise, beam ON, laser OFF




Run 6161 mpwise, beam OFF, laser ON




Run 6161 mpwise, beam OFF, laser OFF




Run 6161 mpwise, beam ON, laser ON




Run 6161 mpwise, beam ON, laser OFF




Run 6161 mpwise, beam OFF, laser ON




Run 6161 mpwise, beam OFF, laser OFF




Run 6161 mpwise, beam ON, laser ON




Run 6161 mpwise, beam ON, laser OFF




Run 6161 mpwise, beam OFF, laser ON




Run 6161 mpwise, beam OFF, laser OFF




Run 6161 mpwise, beam ON, laser ON




Run 6161 mpwise, beam ON, laser OFF




Run 6161 mpwise, beam OFF, laser ON




Run 6161 mpwise, beam OFF, laser OFF




Run 6161 mpwise, beam ON, laser ON



Run 6161 mpwise, beam ON, laser OFF



Run 6161 mpwise, beam OFF, laser ON



Run 6161 mpwise, beam OFF, laser OFF

