




Run 6216 mpwise, acc0: All




Run 6216 mpwise, acc0: Beam OFF




Run 6216, mpwise, acc0: Beam ON, Laser ON




Run 6216, mpwise, acc0: Beam ON, Laser OFF




Run 6216 mpwise, BCM: All




Run 6216 mpwise, BCM: Beam OFF




Run 6216, mpwise, BCM: Beam ON, Laser ON




Run 6216, mpwise, BCM: Beam ON, Laser OFF




Run 6216 mpwise, lasPow: All




Run 6216 mpwise, lasPow: Beam OFF




Run 6216, mpwise, lasPow: Beam ON, Laser ON




Run 6216, mpwise, lasPow: Beam ON, Laser OFF




Run 6216 mpwise, bpmAx: All




Run 6216 mpwise, bpmAx: Beam OFF




Run 6216, mpwise, bpmAx: Beam ON, Laser ON




Run 6216, mpwise, bpmAx: Beam ON, Laser OFF




Run 6216 mpwise, bpmAy: All




Run 6216 mpwise, bpmAy: Beam OFF




Run 6216, mpwise, bpmAy: Beam ON, Laser ON




Run 6216, mpwise, bpmAy: Beam ON, Laser OFF




Run 6216 mpswise, bpmBx: All




Run 6216 mpswise, bpmBx: Beam OFF




Run 6216, mpswise, bpmBx: Beam ON, Laser ON




Run 6216, mpswise, bpmBx: Beam ON, Laser OFF




Run 6216 mpwise, bpmBy: All




Run 6216 mpwise, bpmBy: Beam OFF




Run 6216, mpwise, bpmBy: Beam ON, Laser ON




Run 6216, mpwise, bpmBy: Beam ON, Laser OFF




Run 6216 mpwise, beam ON, laser ON




Run 6216 mpwise, beam ON, laser OFF




Run 6216 mpwise, beam OFF, laser ON




Run 6216 mpwise, beam OFF, laser OFF




Run 6216 mpwise, beam ON, laser ON




Run 6216 mpwise, beam ON, laser OFF




Run 6216 mpwise, beam OFF, laser ON




Run 6216 mpwise, beam OFF, laser OFF




Run 6216 mpwise, beam ON, laser ON




Run 6216 mpwise, beam ON, laser OFF




Run 6216 mpwise, beam OFF, laser ON




Run 6216 mpwise, beam OFF, laser OFF




Run 6216 mpwise, beam ON, laser ON




Run 6216 mpwise, beam ON, laser OFF




Run 6216 mpwise, beam OFF, laser ON




Run 6216 mpwise, beam OFF, laser OFF




Run 6216 mpwise, beam ON, laser ON




Run 6216 mpwise, beam ON, laser OFF




Run 6216 mpwise, beam OFF, laser ON




Run 6216 mpwise, beam OFF, laser OFF




Run 6216 mpwise, beam ON, laser ON




Run 6216 mpwise, beam ON, laser OFF




Run 6216 mpwise, beam OFF, laser ON




Run 6216 mpwise, beam OFF, laser OFF




Run 6216 mpwise, beam ON, laser ON



Run 6216 mpwise, beam ON, laser OFF



Run 6216 mpwise, beam OFF, laser ON



Run 6216 mpwise, beam OFF, laser OFF

