




Run 4402 mpwise, acc0: All




Run 4402 mpwise, acc0: Beam OFF




Run 4402, mpwise, acc0: Beam ON, Laser ON




Run 4402, mpwise, acc0: Beam ON, Laser OFF




Run 4402 mpwise, BCM: All




Run 4402 mpwise, BCM: Beam OFF




Run 4402, mpwise, BCM: Beam ON, Laser ON




Run 4402, mpwise, BCM: Beam ON, Laser OFF




Run 4402 mpwise, lasPow: All




Run 4402 mpwise, lasPow: Beam OFF




Run 4402, mpwise, lasPow: Beam ON, Laser ON




Run 4402, mpwise, lasPow: Beam ON, Laser OFF




Run 4402 mpswise, bpmAx: All




Run 4402 mpswise, bpmAx: Beam OFF




Run 4402, mpswise, bpmAx: Beam ON, Laser ON




Run 4402, mpswise, bpmAx: Beam ON, Laser OFF




Run 4402 mpwise, bpmAy: All




Run 4402 mpwise, bpmAy: Beam OFF




Run 4402, mpwise, bpmAy: Beam ON, Laser ON




Run 4402, mpwise, bpmAy: Beam ON, Laser OFF




Run 4402 mpwise, bpmBx: All




Run 4402 mpwise, bpmBx: Beam OFF



Run 4402, mpwise, bpmBx: Beam ON, Laser ON




Run 4402, mpwise, bpmBx: Beam ON, Laser OFF







Run 4402 mpswise, bpmBy: All




Run 4402 mpswise, bpmBy: Beam OFF




Run 4402, mpswise, bpmBy: Beam ON, Laser ON




Run 4402, mpswise, bpmBy: Beam ON, Laser OFF




Run 4402 mpwise, beam ON, laser ON




Run 4402 mpwise, beam ON, laser OFF



Run 4402 mpwise, beam OFF, laser ON




Run 4402 mpwise, beam OFF, laser OFF







Run 4402 mpwise, beam ON, laser ON




Run 4402 mpwise, beam ON, laser OFF




Run 4402 mpwise, beam OFF, laser ON




Run 4402 mpwise, beam OFF, laser OFF




Run 4402 mpwise, beam ON, laser ON




Run 4402 mpwise, beam ON, laser OFF




Run 4402 mpwise, beam OFF, laser ON




Run 4402 mpwise, beam OFF, laser OFF




Run 4402 mpwise, beam ON, laser ON




Run 4402 mpwise, beam ON, laser OFF




Run 4402 mpwise, beam OFF, laser ON




Run 4402 mpwise, beam OFF, laser OFF




Run 4402 mpwise, beam ON, laser ON




Run 4402 mpwise, beam ON, laser OFF




Run 4402 mpwise, beam OFF, laser ON




Run 4402 mpwise, beam OFF, laser OFF




Run 4402 mpwise, beam ON, laser ON




Run 4402 mpwise, beam ON, laser OFF




Run 4402 mpwise, beam OFF, laser ON




Run 4402 mpwise, beam OFF, laser OFF




Run 4402 mpwise, beam ON, laser ON



Run 4402 mpwise, beam ON, laser OFF



Run 4402 mpwise, beam OFF, laser ON



Run 4402 mpwise, beam OFF, laser OFF

