




Run 5549 mpwise, acc0: All




Run 5549 mpwise, acc0: Beam OFF




Run 5549, mpwise, acc0: Beam ON, Laser ON




Run 5549, mpwise, acc0: Beam ON, Laser OFF




Run 5549 mpwise, BCM: All




Run 5549 mpwise, BCM: Beam OFF




Run 5549, mpwise, BCM: Beam ON, Laser ON




Run 5549, mpwise, BCM: Beam ON, Laser OFF




Run 5549 mpwise, lasPow: All




Run 5549 mpwise, lasPow: Beam OFF




Run 5549, mpwise, lasPow: Beam ON, Laser ON




Run 5549, mpwise, lasPow: Beam ON, Laser OFF




Run 5549 mpwise, bpmAx: All




Run 5549 mpwise, bpmAx: Beam OFF




Run 5549, mpwise, bpmAx: Beam ON, Laser ON




Run 5549, mpwise, bpmAx: Beam ON, Laser OFF




Run 5549 mpwise, bpmAy: All




Run 5549 mpwise, bpmAy: Beam OFF




Run 5549, mpwise, bpmAy: Beam ON, Laser ON




Run 5549, mpwise, bpmAy: Beam ON, Laser OFF




Run 5549 mpwise, bpmBx: All




Run 5549 mpwise, bpmBx: Beam OFF




Run 5549, mpwise, bpmBx: Beam ON, Laser ON




Run 5549, mpwise, bpmBx: Beam ON, Laser OFF




Run 5549 mpwise, bpmBy: All




Run 5549 mpwise, bpmBy: Beam OFF




Run 5549, mpwise, bpmBy: Beam ON, Laser ON




Run 5549, mpwise, bpmBy: Beam ON, Laser OFF




Run 5549 mpwise, beam ON, laser ON




Run 5549 mpwise, beam ON, laser OFF




Run 5549 mpwise, beam OFF, laser ON




Run 5549 mpwise, beam OFF, laser OFF




Run 5549 mpwise, beam ON, laser ON




Run 5549 mpwise, beam ON, laser OFF




Run 5549 mpwise, beam OFF, laser ON




Run 5549 mpwise, beam OFF, laser OFF




Run 5549 mpwise, beam ON, laser ON




Run 5549 mpwise, beam ON, laser OFF




Run 5549 mpwise, beam OFF, laser ON




Run 5549 mpwise, beam OFF, laser OFF




Run 5549 mpwise, beam ON, laser ON




Run 5549 mpwise, beam ON, laser OFF




Run 5549 mpwise, beam OFF, laser ON




Run 5549 mpwise, beam OFF, laser OFF




Run 5549 mpwise, beam ON, laser ON




Run 5549 mpwise, beam ON, laser OFF




Run 5549 mpwise, beam OFF, laser ON




Run 5549 mpwise, beam OFF, laser OFF




Run 5549 mpwise, beam ON, laser ON




Run 5549 mpwise, beam ON, laser OFF




Run 5549 mpwise, beam OFF, laser ON




Run 5549 mpwise, beam OFF, laser OFF




Run 5549 mpwise, beam ON, laser ON



Run 5549 mpwise, beam ON, laser OFF



Run 5549 mpwise, beam OFF, laser ON



Run 5549 mpwise, beam OFF, laser OFF

