




Run 5607 mpwise, acc0: All




Run 5607 mpwise, acc0: Beam OFF




Run 5607, mpwise, acc0: Beam ON, Laser ON




Run 5607, mpwise, acc0: Beam ON, Laser OFF




Run 5607 mpwise, BCM: All




Run 5607 mpwise, BCM: Beam OFF




Run 5607, mpwise, BCM: Beam ON, Laser ON




Run 5607, mpwise, BCM: Beam ON, Laser OFF




Run 5607 mpwise, lasPow: All




Run 5607 mpwise, lasPow: Beam OFF




Run 5607, mpwise, lasPow: Beam ON, Laser ON




Run 5607, mpwise, lasPow: Beam ON, Laser OFF




Run 5607 mpswise, bpmAx: All




Run 5607 mpswise, bpmAx: Beam OFF




Run 5607, mpswise, bpmAx: Beam ON, Laser ON




Run 5607, mpswise, bpmAx: Beam ON, Laser OFF




Run 5607 mpwise, bpmAy: All




Run 5607 mpwise, bpmAy: Beam OFF




Run 5607, mpwise, bpmAy: Beam ON, Laser ON




Run 5607, mpwise, bpmAy: Beam ON, Laser OFF




Run 5607 mpswise, bpmBx: All




Run 5607 mpswise, bpmBx: Beam OFF




Run 5607, mpswise, bpmBx: Beam ON, Laser ON




Run 5607, mpswise, bpmBx: Beam ON, Laser OFF




Run 5607 mpswise, bpmBy: All




Run 5607 mpswise, bpmBy: Beam OFF




Run 5607, mpswise, bpmBy: Beam ON, Laser ON




Run 5607, mpswise, bpmBy: Beam ON, Laser OFF




Run 5607 mpwise, beam ON, laser ON




Run 5607 mpwise, beam ON, laser OFF




Run 5607 mpwise, beam OFF, laser ON




Run 5607 mpwise, beam OFF, laser OFF




Run 5607 mpwise, beam ON, laser ON




Run 5607 mpwise, beam ON, laser OFF




Run 5607 mpwise, beam OFF, laser ON




Run 5607 mpwise, beam OFF, laser OFF




Run 5607 mpwise, beam ON, laser ON




Run 5607 mpwise, beam ON, laser OFF




Run 5607 mpwise, beam OFF, laser ON




Run 5607 mpwise, beam OFF, laser OFF




Run 5607 mpwise, beam ON, laser ON




Run 5607 mpwise, beam ON, laser OFF




Run 5607 mpwise, beam OFF, laser ON




Run 5607 mpwise, beam OFF, laser OFF




Run 5607 mpwise, beam ON, laser ON




Run 5607 mpwise, beam ON, laser OFF




Run 5607 mpwise, beam OFF, laser ON




Run 5607 mpwise, beam OFF, laser OFF




Run 5607 mpwise, beam ON, laser ON




Run 5607 mpwise, beam ON, laser OFF




Run 5607 mpwise, beam OFF, laser ON




Run 5607 mpwise, beam OFF, laser OFF




Run 5607 mpwise, beam ON, laser ON



Run 5607 mpwise, beam ON, laser OFF



Run 5607 mpwise, beam OFF, laser ON



Run 5607 mpwise, beam OFF, laser OFF

