




Run 5647 mpwise, acc0: All




Run 5647 mpwise, acc0: Beam OFF




Run 5647, mpwise, acc0: Beam ON, Laser ON




Run 5647, mpwise, acc0: Beam ON, Laser OFF




Run 5647 mpwise, BCM: All




Run 5647 mpwise, BCM: Beam OFF




Run 5647, mpwise, BCM: Beam ON, Laser ON




Run 5647, mpwise, BCM: Beam ON, Laser OFF




Run 5647 mpwise, lasPow: All




Run 5647 mpwise, lasPow: Beam OFF




Run 5647, mpwise, lasPow: Beam ON, Laser ON




Run 5647, mpwise, lasPow: Beam ON, Laser OFF




Run 5647 mpwise, bpmAx: All




Run 5647 mpwise, bpmAx: Beam OFF




Run 5647, mpwise, bpmAx: Beam ON, Laser ON




Run 5647, mpwise, bpmAx: Beam ON, Laser OFF




Run 5647 mpwise, bpmAy: All




Run 5647 mpwise, bpmAy: Beam OFF




Run 5647, mpwise, bpmAy: Beam ON, Laser ON




Run 5647, mpwise, bpmAy: Beam ON, Laser OFF




Run 5647 mpwise, bpmBx: All




Run 5647 mpwise, bpmBx: Beam OFF




Run 5647, mpwise, bpmBx: Beam ON, Laser ON




Run 5647, mpwise, bpmBx: Beam ON, Laser OFF




Run 5647 mpwise, bpmBy: All




Run 5647 mpwise, bpmBy: Beam OFF




Run 5647, mpwise, bpmBy: Beam ON, Laser ON




Run 5647, mpwise, bpmBy: Beam ON, Laser OFF




Run 5647 mpswise, beam ON, laser ON




Run 5647 mpswise, beam ON, laser OFF




Run 5647 mpswise, beam OFF, laser ON




Run 5647 mpswise, beam OFF, laser OFF




Run 5647 mpwise, beam ON, laser ON




Run 5647 mpwise, beam ON, laser OFF




Run 5647 mpwise, beam OFF, laser ON




Run 5647 mpwise, beam OFF, laser OFF




Run 5647 mpwise, beam ON, laser ON




Run 5647 mpwise, beam ON, laser OFF




Run 5647 mpwise, beam OFF, laser ON




Run 5647 mpwise, beam OFF, laser OFF




Run 5647 mpwise, beam ON, laser ON




Run 5647 mpwise, beam ON, laser OFF




Run 5647 mpwise, beam OFF, laser ON




Run 5647 mpwise, beam OFF, laser OFF




Run 5647 mpwise, beam ON, laser ON




Run 5647 mpwise, beam ON, laser OFF




Run 5647 mpwise, beam OFF, laser ON




Run 5647 mpwise, beam OFF, laser OFF




Run 5647 mpwise, beam ON, laser ON




Run 5647 mpwise, beam ON, laser OFF




Run 5647 mpwise, beam OFF, laser ON




Run 5647 mpwise, beam OFF, laser OFF




Run 5647 mpwise, beam ON, laser ON



Run 5647 mpwise, beam ON, laser OFF



Run 5647 mpwise, beam OFF, laser ON



Run 5647 mpwise, beam OFF, laser OFF

