




Run 5664 mpwise, acc0: All




Run 5664 mpwise, acc0: Beam OFF




Run 5664, mpwise, acc0: Beam ON, Laser ON




Run 5664, mpwise, acc0: Beam ON, Laser OFF




Run 5664 mpwise, BCM: All




Run 5664 mpwise, BCM: Beam OFF




Run 5664, mpwise, BCM: Beam ON, Laser ON




Run 5664, mpwise, BCM: Beam ON, Laser OFF




Run 5664 mpwise, lasPow: All




Run 5664 mpwise, lasPow: Beam OFF




Run 5664, mpwise, lasPow: Beam ON, Laser ON




Run 5664, mpwise, lasPow: Beam ON, Laser OFF




Run 5664 mpwise, bpmAx: All




Run 5664 mpwise, bpmAx: Beam OFF




Run 5664, mpwise, bpmAx: Beam ON, Laser ON




Run 5664, mpwise, bpmAx: Beam ON, Laser OFF




Run 5664 mpwise, bpmAy: All




Run 5664 mpwise, bpmAy: Beam OFF




Run 5664, mpwise, bpmAy: Beam ON, Laser ON




Run 5664, mpwise, bpmAy: Beam ON, Laser OFF




Run 5664 mpswise, bpmBx: All




Run 5664 mpswise, bpmBx: Beam OFF



Run 5664, mpswise, bpmBx: Beam ON, Laser ON




Run 5664, mpswise, bpmBx: Beam ON, Laser OFF







Run 5664 mpswise, bpmBy: All




Run 5664 mpswise, bpmBy: Beam OFF




Run 5664, mpswise, bpmBy: Beam ON, Laser ON




Run 5664, mpswise, bpmBy: Beam ON, Laser OFF




Run 5664 mpwise, beam ON, laser ON




Run 5664 mpwise, beam ON, laser OFF



Run 5664 mpwise, beam OFF, laser ON




Run 5664 mpwise, beam OFF, laser OFF







Run 5664 mpwise, beam ON, laser ON




Run 5664 mpwise, beam ON, laser OFF




Run 5664 mpwise, beam OFF, laser ON




Run 5664 mpwise, beam OFF, laser OFF




Run 5664 mpwise, beam ON, laser ON




Run 5664 mpwise, beam ON, laser OFF




Run 5664 mpwise, beam OFF, laser ON




Run 5664 mpwise, beam OFF, laser OFF




Run 5664 mpwise, beam ON, laser ON




Run 5664 mpwise, beam ON, laser OFF




Run 5664 mpwise, beam OFF, laser ON




Run 5664 mpwise, beam OFF, laser OFF




Run 5664 mpwise, beam ON, laser ON




Run 5664 mpwise, beam ON, laser OFF




Run 5664 mpwise, beam OFF, laser ON




Run 5664 mpwise, beam OFF, laser OFF




Run 5664 mpwise, beam ON, laser ON




Run 5664 mpwise, beam ON, laser OFF




Run 5664 mpwise, beam OFF, laser ON




Run 5664 mpwise, beam OFF, laser OFF




Run 5664 mpwise, beam ON, laser ON



Run 5664 mpwise, beam ON, laser OFF



Run 5664 mpwise, beam OFF, laser ON



Run 5664 mpwise, beam OFF, laser OFF

