




Run 5897 mpwise, acc0: All




Run 5897 mpwise, acc0: Beam OFF




Run 5897, mpwise, acc0: Beam ON, Laser ON




Run 5897, mpwise, acc0: Beam ON, Laser OFF




Run 5897 mpswise, BCM: All




Run 5897 mpswise, BCM: Beam OFF




Run 5897, mpswise, BCM: Beam ON, Laser ON




Run 5897, mpswise, BCM: Beam ON, Laser OFF




Run 5897 mpwise, lasPow: All




Run 5897 mpwise, lasPow: Beam OFF




Run 5897, mpwise, lasPow: Beam ON, Laser ON




Run 5897, mpwise, lasPow: Beam ON, Laser OFF




Run 5897 mpwise, bpmAx: All




Run 5897 mpwise, bpmAx: Beam OFF




Run 5897, mpwise, bpmAx: Beam ON, Laser ON




Run 5897, mpwise, bpmAx: Beam ON, Laser OFF




Run 5897 mpwise, bpmAy: All




Run 5897 mpwise, bpmAy: Beam OFF




Run 5897, mpwise, bpmAy: Beam ON, Laser ON




Run 5897, mpwise, bpmAy: Beam ON, Laser OFF




Run 5897 mpwise, bpmBx: All




Run 5897 mpwise, bpmBx: Beam OFF




Run 5897, mpwise, bpmBx: Beam ON, Laser ON




Run 5897, mpwise, bpmBx: Beam ON, Laser OFF




Run 5897 mpwise, bpmBy: All




Run 5897 mpwise, bpmBy: Beam OFF




Run 5897, mpwise, bpmBy: Beam ON, Laser ON




Run 5897, mpwise, bpmBy: Beam ON, Laser OFF




Run 5897 mpwise, beam ON, laser ON




Run 5897 mpwise, beam ON, laser OFF




Run 5897 mpwise, beam OFF, laser ON




Run 5897 mpwise, beam OFF, laser OFF




Run 5897 mpwise, beam ON, laser ON




Run 5897 mpwise, beam ON, laser OFF




Run 5897 mpwise, beam OFF, laser ON




Run 5897 mpwise, beam OFF, laser OFF




Run 5897 mpswise, beam ON, laser ON




Run 5897 mpswise, beam ON, laser OFF




Run 5897 mpswise, beam OFF, laser ON




Run 5897 mpswise, beam OFF, laser OFF




Run 5897 mpwise, beam ON, laser ON




Run 5897 mpwise, beam ON, laser OFF




Run 5897 mpwise, beam OFF, laser ON




Run 5897 mpwise, beam OFF, laser OFF




Run 5897 mpwise, beam ON, laser ON




Run 5897 mpwise, beam ON, laser OFF




Run 5897 mpwise, beam OFF, laser ON




Run 5897 mpwise, beam OFF, laser OFF




Run 5897 mpwise, beam ON, laser ON




Run 5897 mpwise, beam ON, laser OFF




Run 5897 mpwise, beam OFF, laser ON




Run 5897 mpwise, beam OFF, laser OFF




Run 5897 mpwise, beam ON, laser ON



Run 5897 mpwise, beam ON, laser OFF



Run 5897 mpwise, beam OFF, laser ON



Run 5897 mpwise, beam OFF, laser OFF

