




Run 5936 mpwise, acc0: All




Run 5936 mpwise, acc0: Beam OFF




Run 5936, mpwise, acc0: Beam ON, Laser ON




Run 5936, mpwise, acc0: Beam ON, Laser OFF




Run 5936 mpwise, BCM: All




Run 5936 mpwise, BCM: Beam OFF




Run 5936, mpwise, BCM: Beam ON, Laser ON




Run 5936, mpwise, BCM: Beam ON, Laser OFF




Run 5936 mpwise, lasPow: All




Run 5936 mpwise, lasPow: Beam OFF




Run 5936, mpwise, lasPow: Beam ON, Laser ON




Run 5936, mpwise, lasPow: Beam ON, Laser OFF




Run 5936 mpwise, bpmAx: All




Run 5936 mpwise, bpmAx: Beam OFF




Run 5936, mpwise, bpmAx: Beam ON, Laser ON




Run 5936, mpwise, bpmAx: Beam ON, Laser OFF




Run 5936 mpwise, bpmAy: All




Run 5936 mpwise, bpmAy: Beam OFF




Run 5936, mpwise, bpmAy: Beam ON, Laser ON




Run 5936, mpwise, bpmAy: Beam ON, Laser OFF




Run 5936 mpswise, bpmBx: All




Run 5936 mpswise, bpmBx: Beam OFF




Run 5936, mpswise, bpmBx: Beam ON, Laser ON




Run 5936, mpswise, bpmBx: Beam ON, Laser OFF




Run 5936 mpwise, bpmBy: All




Run 5936 mpwise, bpmBy: Beam OFF




Run 5936, mpwise, bpmBy: Beam ON, Laser ON




Run 5936, mpwise, bpmBy: Beam ON, Laser OFF




Run 5936 mpwise, beam ON, laser ON




Run 5936 mpwise, beam ON, laser OFF




Run 5936 mpwise, beam OFF, laser ON




Run 5936 mpwise, beam OFF, laser OFF




Run 5936 mpwise, beam ON, laser ON




Run 5936 mpwise, beam ON, laser OFF




Run 5936 mpwise, beam OFF, laser ON




Run 5936 mpwise, beam OFF, laser OFF




Run 5936 mpwise, beam ON, laser ON




Run 5936 mpwise, beam ON, laser OFF




Run 5936 mpwise, beam OFF, laser ON




Run 5936 mpwise, beam OFF, laser OFF




Run 5936 mpswise, beam ON, laser ON




Run 5936 mpswise, beam ON, laser OFF




Run 5936 mpswise, beam OFF, laser ON




Run 5936 mpswise, beam OFF, laser OFF




Run 5936 mpwise, beam ON, laser ON




Run 5936 mpwise, beam ON, laser OFF




Run 5936 mpwise, beam OFF, laser ON




Run 5936 mpwise, beam OFF, laser OFF




Run 5936 mpwise, beam ON, laser ON




Run 5936 mpwise, beam ON, laser OFF




Run 5936 mpwise, beam OFF, laser ON




Run 5936 mpwise, beam OFF, laser OFF




Run 5936 mpwise, beam ON, laser ON



Run 5936 mpwise, beam ON, laser OFF



Run 5936 mpwise, beam OFF, laser ON



Run 5936 mpwise, beam OFF, laser OFF

