




Run 5975 mpwise, acc0: All




Run 5975 mpwise, acc0: Beam OFF




Run 5975, mpwise, acc0: Beam ON, Laser ON




Run 5975, mpwise, acc0: Beam ON, Laser OFF




Run 5975 mpwise, BCM: All




Run 5975 mpwise, BCM: Beam OFF




Run 5975, mpwise, BCM: Beam ON, Laser ON




Run 5975, mpwise, BCM: Beam ON, Laser OFF




Run 5975 mpswise, lasPow: All




Run 5975 mpswise, lasPow: Beam OFF




Run 5975, mpswise, lasPow: Beam ON, Laser ON




Run 5975, mpswise, lasPow: Beam ON, Laser OFF




Run 5975 mpwise, bpmAx: All




Run 5975 mpwise, bpmAx: Beam OFF




Run 5975, mpwise, bpmAx: Beam ON, Laser ON




Run 5975, mpwise, bpmAx: Beam ON, Laser OFF




Run 5975 mpwise, bpmAy: All




Run 5975 mpwise, bpmAy: Beam OFF




Run 5975, mpwise, bpmAy: Beam ON, Laser ON




Run 5975, mpwise, bpmAy: Beam ON, Laser OFF




Run 5975 mpwise, bpmBx: All




Run 5975 mpwise, bpmBx: Beam OFF



Run 5975, mpwise, bpmBx: Beam ON, Laser ON




Run 5975, mpwise, bpmBx: Beam ON, Laser OFF







Run 5975 mpwise, bpmBy: All




Run 5975 mpwise, bpmBy: Beam OFF




Run 5975, mpwise, bpmBy: Beam ON, Laser ON




Run 5975, mpwise, bpmBy: Beam ON, Laser OFF




Run 5975 mpwise, beam ON, laser ON




Run 5975 mpwise, beam ON, laser OFF



Run 5975 mpwise, beam OFF, laser ON




Run 5975 mpwise, beam OFF, laser OFF







Run 5975 mpswise, beam ON, laser ON




Run 5975 mpswise, beam ON, laser OFF




Run 5975 mpswise, beam OFF, laser ON




Run 5975 mpswise, beam OFF, laser OFF




Run 5975 mpwise, beam ON, laser ON




Run 5975 mpwise, beam ON, laser OFF




Run 5975 mpwise, beam OFF, laser ON




Run 5975 mpwise, beam OFF, laser OFF




Run 5975 mpwise, beam ON, laser ON




Run 5975 mpwise, beam ON, laser OFF




Run 5975 mpwise, beam OFF, laser ON




Run 5975 mpwise, beam OFF, laser OFF




Run 5975 mpwise, beam ON, laser ON




Run 5975 mpwise, beam ON, laser OFF




Run 5975 mpwise, beam OFF, laser ON




Run 5975 mpwise, beam OFF, laser OFF




Run 5975 mpwise, beam ON, laser ON




Run 5975 mpwise, beam ON, laser OFF




Run 5975 mpwise, beam OFF, laser ON




Run 5975 mpwise, beam OFF, laser OFF




Run 5975 mpwise, beam ON, laser ON



Run 5975 mpwise, beam ON, laser OFF



Run 5975 mpwise, beam OFF, laser ON



Run 5975 mpwise, beam OFF, laser OFF

