




Run 5986 mpwise, acc0: All




Run 5986 mpwise, acc0: Beam OFF




Run 5986, mpwise, acc0: Beam ON, Laser ON




Run 5986, mpwise, acc0: Beam ON, Laser OFF




Run 5986 mpwise, BCM: All




Run 5986 mpwise, BCM: Beam OFF




Run 5986, mpwise, BCM: Beam ON, Laser ON




Run 5986, mpwise, BCM: Beam ON, Laser OFF




Run 5986 mpwise, lasPow: All




Run 5986 mpwise, lasPow: Beam OFF




Run 5986, mpwise, lasPow: Beam ON, Laser ON




Run 5986, mpwise, lasPow: Beam ON, Laser OFF




Run 5986 mpwise, bpmAx: All




Run 5986 mpwise, bpmAx: Beam OFF




Run 5986, mpwise, bpmAx: Beam ON, Laser ON




Run 5986, mpwise, bpmAx: Beam ON, Laser OFF




Run 5986 mpwise, bpmAy: All




Run 5986 mpwise, bpmAy: Beam OFF




Run 5986, mpwise, bpmAy: Beam ON, Laser ON




Run 5986, mpwise, bpmAy: Beam ON, Laser OFF




Run 5986 mpwise, bpmBx: All




Run 5986 mpwise, bpmBx: Beam OFF




Run 5986, mpwise, bpmBx: Beam ON, Laser ON




Run 5986, mpwise, bpmBx: Beam ON, Laser OFF




Run 5986 mpwise, bpmBy: All




Run 5986 mpwise, bpmBy: Beam OFF




Run 5986, mpwise, bpmBy: Beam ON, Laser ON




Run 5986, mpwise, bpmBy: Beam ON, Laser OFF




Run 5986 mpswise, beam ON, laser ON




Run 5986 mpswise, beam ON, laser OFF




Run 5986 mpswise, beam OFF, laser ON




Run 5986 mpswise, beam OFF, laser OFF




Run 5986 mpwise, beam ON, laser ON




Run 5986 mpwise, beam ON, laser OFF




Run 5986 mpwise, beam OFF, laser ON




Run 5986 mpwise, beam OFF, laser OFF




Run 5986 mpswise, beam ON, laser ON




Run 5986 mpswise, beam ON, laser OFF




Run 5986 mpswise, beam OFF, laser ON




Run 5986 mpswise, beam OFF, laser OFF




Run 5986 mpwise, beam ON, laser ON




Run 5986 mpwise, beam ON, laser OFF




Run 5986 mpwise, beam OFF, laser ON




Run 5986 mpwise, beam OFF, laser OFF




Run 5986 mpwise, beam ON, laser ON




Run 5986 mpwise, beam ON, laser OFF




Run 5986 mpwise, beam OFF, laser ON




Run 5986 mpwise, beam OFF, laser OFF




Run 5986 mpwise, beam ON, laser ON




Run 5986 mpwise, beam ON, laser OFF




Run 5986 mpwise, beam OFF, laser ON




Run 5986 mpwise, beam OFF, laser OFF




Run 5986 mpwise, beam ON, laser ON



Run 5986 mpwise, beam ON, laser OFF



Run 5986 mpwise, beam OFF, laser ON



Run 5986 mpwise, beam OFF, laser OFF

