




Run 6197 mpwise, acc0: All




Run 6197 mpwise, acc0: Beam OFF




Run 6197, mpwise, acc0: Beam ON, Laser ON




Run 6197, mpwise, acc0: Beam ON, Laser OFF




Run 6197 mpwise, BCM: All




Run 6197 mpwise, BCM: Beam OFF




Run 6197, mpwise, BCM: Beam ON, Laser ON




Run 6197, mpwise, BCM: Beam ON, Laser OFF




Run 6197 mpwise, lasPow: All




Run 6197 mpwise, lasPow: Beam OFF




Run 6197, mpwise, lasPow: Beam ON, Laser ON




Run 6197, mpwise, lasPow: Beam ON, Laser OFF




Run 6197 mpwise, bpmAx: All




Run 6197 mpwise, bpmAx: Beam OFF




Run 6197, mpwise, bpmAx: Beam ON, Laser ON




Run 6197, mpwise, bpmAx: Beam ON, Laser OFF




Run 6197 mpwise, bpmAy: All




Run 6197 mpwise, bpmAy: Beam OFF




Run 6197, mpwise, bpmAy: Beam ON, Laser ON




Run 6197, mpwise, bpmAy: Beam ON, Laser OFF




Run 6197 mpswise, bpmBx: All




Run 6197 mpswise, bpmBx: Beam OFF



Run 6197, mpswise, bpmBx: Beam ON, Laser ON




Run 6197, mpswise, bpmBx: Beam ON, Laser OFF







Run 6197 mpwise, bpmBy: All




Run 6197 mpwise, bpmBy: Beam OFF




Run 6197, mpwise, bpmBy: Beam ON, Laser ON




Run 6197, mpwise, bpmBy: Beam ON, Laser OFF




Run 6197 mpwise, beam ON, laser ON




Run 6197 mpwise, beam ON, laser OFF



Run 6197 mpwise, beam OFF, laser ON




Run 6197 mpwise, beam OFF, laser OFF







Run 6197 mpwise, beam ON, laser ON




Run 6197 mpwise, beam ON, laser OFF




Run 6197 mpwise, beam OFF, laser ON




Run 6197 mpwise, beam OFF, laser OFF




Run 6197 mpwise, beam ON, laser ON




Run 6197 mpwise, beam ON, laser OFF




Run 6197 mpwise, beam OFF, laser ON




Run 6197 mpwise, beam OFF, laser OFF




Run 6197 mpwise, beam ON, laser ON




Run 6197 mpwise, beam ON, laser OFF




Run 6197 mpwise, beam OFF, laser ON




Run 6197 mpwise, beam OFF, laser OFF




Run 6197 mpwise, beam ON, laser ON




Run 6197 mpwise, beam ON, laser OFF




Run 6197 mpwise, beam OFF, laser ON




Run 6197 mpwise, beam OFF, laser OFF




Run 6197 mpwise, beam ON, laser ON




Run 6197 mpwise, beam ON, laser OFF




Run 6197 mpwise, beam OFF, laser ON




Run 6197 mpwise, beam OFF, laser OFF




Run 6197 mpwise, beam ON, laser ON



Run 6197 mpwise, beam ON, laser OFF



Run 6197 mpwise, beam OFF, laser ON



Run 6197 mpwise, beam OFF, laser OFF

