




Run 4496 mpwise, acc0: All




Run 4496 mpwise, acc0: Beam OFF




Run 4496 mpwise, acc0: Beam ON, Laser ON




Run 4496 mpwise, acc0: Beam ON, Laser OFF




Run 4496 mpwise, Acc0/NAcc0:mpsCoda, beam ON, laser OFF



Run 4496 mpwise, Acc0/NAcc0:mpsCoda, beam OFF



Run 4496 mpwise, Acc0/NAcc0:mpsCoda, beam ON, laser ON



Run 4496 mpwise, Acc0/NAcc0:mpsCoda, beam ON, laser OFF

